SeeMeCNC Guides

DUET reset bed map for 'first probe' macro

Written By: SeeMeCNC

F Tools /	Heaters / +	Extra		≡ 0	Contro	I All 👻	Temperature C	Chart		Machine Status				
Tool	Heater	Current	Activ	/e	Sta	ndby	250			Head	х	Y	z	
Tool 0 -	Heater 1 active	25.5 °C	0	•	0	-	200			Position	n/a	n/a	n/a	
Bed	Heater 0	26.3 °C	0	•			150			Extruder	Drive 0			
Deu	active	20.0 C	0				100			Drives			10706.5	
		50								Sensors		Vin Z-F		
											12.9 V		0	
Machine	Control	General	User Ir	nterfac	e	List Items	System Edit	tor	Machine Properties	Tools				
Print Stat	us	System	n Directory									New File	C Refres	
G_Code (G-Code Console		lame ↓⁵					Size	e	Last modified				
G-Code Files		🗆 🖺 b	ed.g					285 B 4/7/2018, 9:24:17 PM						
			ancel.g		-			45 B 4/7/2018, 9:24:17 PM						
S Macros	' Macros		onfig-overri	ide.g				520 B 4/23/2018, 10:47:25 AM						
Filaments			onfig.g				3.0 KiB			5/3/2018, 11:25:17 AM				
Settings			onfig.g.bak					3.0	KiB	5/3/2018, 8:57:13 AM				
			uetWiFiSer	rver.bir	ı		289.9 KiB 856 B 380 B 59.5 KiB 60.0 KiB 27 B			4/6/2018, 10:54:07 AM 4/23/2018, 10:46:25 AM 4/7/2018, 9:24:17 PM 4/7/2018, 9:24:17 PM 4/7/2018, 9:24:17 PM				
		🔲 🖺 h	eightmap.c	sv										
		🔲 🖺 h	omedelta.g	l.										
		🔲 🖺 ia	p.bin											
		🔲 🖺 ia	p4e.bin											
			ause.g							4/7/2018, 9:24:17 PM				
		🔲 🖺 re	esume.g					28 E	3	4/7/2018, 9:24:17 P	4/7/2018, 9:24:17 PM			
		-	r000 a					126		4/7/0010 0·04·17 D				

This document was generated on 2021-12-21 08:02:51 PM (MST).

Step 1 — Delete config-override.g

C+ Disconne	E Disconnect Send G-Code				Upload & Prin	t	A	rtemis	A	Idle	∳ Em	ergency STC			
F Tools /							ture Cha	art		Machine Status					
Tool	Heater	Curr	ent A	ctive	Standb	y 250				Head	x	Y			
Tool 0 -	Heater 1	25.5	°C 0	-	0	• 200				Position	n/a	n/a	n/a		
	Heater 0	05.0				150				Extruder	Drive 0				
Bed active		26.3	°C 0	•		100				Drives	n/a		10706.5		
						50	50				Vin		Z-Probe		
						Ŷ			12.9 V		0				
A Machine	Control	Gen	ieral Us	er Interfa	ace Lis	t Items System	rties	Tools							
Print Status G-Code Console		a s	system Dire	tory					li i	New File	C Refresh				
			File Name	2				Size	Last modified						
	G-Code Files		bed.g				3	285 B	4/7	4/7/2018, 9:24:17 PM					
			cancel.g		1			45 B 4/7/2018, 9:24:17 PM							
Ø Macros			config-o	verride.g	-		520 B			4/23/2018, 10:47:25 AM					
Filaments			config.g				3.0 KIB			5/3/2018, 11:25:17 AM					
Settings			config.g	bak				3.0 KIB	5/3	5/3/2018, 8:57:13 AM					
			DuetWif	iServer.	bin		289.9 KiB			4/6/2018, 10:54:07 AM					
			heightm	ap.csv				856 B	4/2	4/23/2018, 10:46:25 AM					
			homede	Ita.g				380 B 4/7/2018, 9:24:17 PM							
			iap.bin					59.5 KIB 4/7/2018, 9:24:17 PM							
		8	lap4e.bl	'n						4/7/2018, 9:24:17 PM 4/7/2018, 9:24:17 PM					
			pause.g												
			resume.	g			1	28 B	4/7	7/2018, 9:24:17 PI	v				
			Hroot a					496 D	40	7/0040 0-04-47 0					

- Open the system editor
- delete the file named "configoverride.g" in the picture attached.
- also delete the file that says
 "heightmap.csv"
- press "Emergency Stop" button to reset the Duet control board.

Step 2 — run 'first probe' macro

	Heaters / +		Trent Active Standby						Temperat	Stick				Machine Statu				
Tool	Heater	Curren	t.	Activ	e	Sta	andby		250					Head Position	x	Y	Z	
Tool 0 -	Heater 1 active	25.8 °C		0	*	0	-		200					Position	n/a	n/a	n/a	
Bed	Heater 0	25.2 °C		0 -					150					Extruder Drives	Drive 0			
active									50					Diries	n/a		10706.5 Z-Probe	
														Sensors	Vin			
															12.9 V		0	
Machine	Control					Head	d Move	ment				Auto I	Delta Calibration	•	User-D	efined Macr	os	
Print Status G-Code Console G-Code Files Macros													Fila					
		《 X-10 《 X-1			K X-0.1			X+	0.1 >	×	+1 >	X+10 >						
														First Probe				
		<	< Y-10 < Y-1				4 Y-0.1			Y+0.1 > Y+1 > Y+10					NETWORK			
		< :	Z-10 < Z-1				< Z-0.1			Z+0.1.2+1.> Z+10.>					Preheat Bed ABS			
		A	A ==												Preheat Bed PLA			
Filaments		ZA The	A The following axes are not homed: X, Y, Z												Probe Autolevel			
Settings		Extruder Control											Unlock Steppers					
		Feed an	nount	in mm:				Fee	edrate in	nm/sec:			† Retract	t	Update Firmware			
		100	50	20	10	5	1	6	0 30	15	5	1	+ Extrude					
											_	_		_	Misi	cellaneous		
														Fan 0	0 %			
															•			

- clear the nozzle and clear the bed
- Be sure the bed and nozzle at room temperature, not hot
- Choose "Machine Control"
- click the "First Probe" macro
- Wait for probing to finish. Once complete, shut the machine completely off using the power switch, wait 30 seconds, power it back on and reconnect.
- You are now ready to start printing!

This document was generated on 2021-12-21 08:02:51 PM (MST).