SeeMeCNC Guides **DUET Setting up Macros**

How to create Macros on the Duet web interface.

Written By: SeeMeCNC

C Disconnect Send G-Code				•	A Send	Upload & Print	nt	Artemis5	1 🛕	ldle	Femergency STC				
🗲 Tools	/ 🜖 Heaters	/ + E>	ktra		≡	Cont	rol All 👻	Temperature Ch	art		Machine Stat	us			
Tool	Heater	Curre	ent	Active		Standby		250			Head	х	Y	z	
	Heater 1	25.5	25.5 °C 0 ▼ 25.5 °C 0 ▼			0	•	200			Position	n/a	n/a	n/a	
	1							150			Extruder	Drive 0	Drive 1		
T1	active	25.5	°C	0	•	0	•	100	Size		Drives	n/a	0.0	0.0	
Bed	Heater 0	22.8	°C	0	•			50			Sensors	Vin		0.0 Z-Probe 0 ke new	
								0				13.0 V		0	
Machin	e Control	2	Macr	os Dir	ectory					🗲 Go Up	🔷 Upload	Macro File (s)) + Ma	ake new	
Print St	atus		File	Name	↓ ⁿ z				Size	Last m	odified	Directory Macro			
Tool 0 ~ Heater 1 active Tool 1 ~ Heater 1 active		F	First P	robe				247 B	12/28/2	2017, 2:48:09 P	м	Create a new mac			
G-Code	e Files		F F	Prehea	at Bed	ABS			47 B	12/28/2	2017, 7:06:24 P	М			
Macros	S	5	E F	Prehea	at Bed	PLA			45 B	12/28/2	2017, 7:06:24 P	М			

Step 1 — Method 1: Copy and Paste

Artemis:	1	× (0 A	rtemis/Filamen	t Load X					37	× × – m	💧 Artemi	\$51	×\Q	Artemis/Filamen	nt Load 🛛 🗙						3	× - 500
· > C	(i) 10.73.29	.51							\$	I • :	$\leftrightarrow \ \Rightarrow \ G$	③ Not sec	ure 10.7	3.29.51							☆ 🔤	
C+ Disconn	ect Sen	d G-Code			Upload & Print	Artemis	51 🔺	Idle	🗲 Emerge	ency STOP	C+ Discon	nect Se			- 4	Send Doload & P	rint A	Artemis5	j1 🔺	Idle	∳ Emerg	jency STOP
F Tools /	b Heaters	/ 🕇 Extra		Control All 👻	Temperature Chart		Machine Stat	us			≁ Tools	/ 🔄 Heaters	/ + Extr	a 🔳	Control	Her music			Machine Stat	us		
Tool	Heater	Current	Active	Standby	250		Head Position	x	Y	z				t Active		Please enter a filename			Head	x		z
Tool 0 +	Heater 1 active	25.5 °C	0 •	0 -	200			n/a	n/a	n/a	<u>Tool 0</u> +	Heater 1 active	25.5 °C	0 -	0	Filament Load						n/a
	Heater 1	25.5 °C	0 -	0 -	150		Extruder Drives	Drive 0	Drive 1 0.0	0.0	Tool 1-	Heater 1	25.5 °C	0 -	0				Extruder			
					50			Vin		Z-Probe						~ 0	K X Cancel			Head losition X Y m/a m/a m/a txtruder lorives Drive 0 Drive 1 m/a 0.0 Vir istasson 13.0 V istasson chuptassi Macro File(s)	Z-Probe	
Bed	off	22.8 °C	0 +		0		Sensors		V 0		Bed	off	22.9 °C	0 -		0	_	-	Sensors			0
			cros Directory	0		📽 Go Up		Macro File (s	s) 🕂 Ma	ake new -	A Machin			Macros Directory	y					Macro File(s) + M	ike new
Print Sta	tus		e Name 🚦		Siz		nodified		Macro		Print S			File Name 1 ^ª			Size		nodified			
Tool 0+ Heater 1 2 Tool 1+ Heater 1 2 Bed Heater 0 2 R Machine Control Print Status 2_ G-Code Console		First Probe		24	'B 12/28	12/28/2017, 2:48:09 PM			Create a new macro file				First Probe		247 B	12/28/2017, 2:48:09 PM						
		Preheat Bec	ABS	47	B 12/28	2017, 7:06:24 P	м			G-Code	e Files		Preheat Bed ABS			47 B	12/28/	2017, 7:06:24 PI	24 PM			
9 Macros	G		Preheat Bec	PLA	45	B 12/28	2017, 7:06:24 P	м			8 Macros	a		🔲 불 Preheat Bed PLA			45 B	B 12/28/2017, 7:06:24				
Filament	S										Filame	nts										
Settings											Setting	s										

- Click on the "Macros" link on the left of the screen to enter the Macro list.
- Click the button on the right labled "Make new..." and on the drop down menu that appears, click "Macro".
- You will be prompted to name the macro. Enter a name in the box and click OK.

Step 2 — Method 1, continued

		<i>w</i>	× C Artemis/Filament Load ×				Rgan - + ×
	→ C 🛈 Not secure 10.73.29.51 🗴 🔳 🔮	← → C ① Not secur	ire 10.73.29.51			4	
Artemis X Artemis Filamert Load X III Artemis Filamert Load X III Artemis Biolob/master/SD/macros/Filament%20Load X IIII Artemis Biolob/master/SD/macros/Filament%20Load X IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII		C+ Disconnect Send	d G-Code 🔹 🔺 Se	nd Print Ar	emis51 🔺	Idle 🗲 E	Emergency STOP
💽 This repository Sourch Pull requests Issues Marketplace Explore 🙎 + • • •	Editing 0:/macros/Filament Load	/ Tools / 4) Heaters	/ + Extra E Control All +	Temperature Chart	Machine	Status	
V ind repository Solution Pull requests issues warkedpace Explore	628		Current Active Standby	250	Head		Y Z
© Unwatch + 3 ★ Star 0 ¥ Fork 0	M291 P"Insert filament just past the EZR, then click OK" R"Load Filament" S3	Tool 0 - Heater 1 To active	25.3 °C 0 • 0 •	200	Extrude	iva i	n/a n/a
↔ Code ① Issues @ 17 Pull requests @ Projects @ 11 Wilki da Insights O Settings	M109 5220 M83	Tool 1 - Heater 1 T1 active	25.3 °C 0 • 0 •	150	Drives	A	0.0 0.0
Branch: master Artemis / SD / macros / Filament Load Find the Copy path Copy path	01 E710 F5000 G1 E50 F150 M82	Bed Heater 0	22.9 °C 0 •	50	Sensor	8 Vin 13.0 V	Z-Probe
Ryan Rittenhouse Added filament load and unload macros assbose a minute ago	A Machine Control	Head Movern	er# Auto Deta Cal	ration -	User-Defined	Macros	
0 contributors	M104 50 M84	A Print Status	Home All Home	X Home Y Hor	e Z	Filament L	.cad
13 lines (11 sloc) 150 Bytes Raw Biame History 🖌 🍸			< X-10 < X-1 < X	0.1 X+0.1 > X+1 >	+10 >	First Pro	be .
1 2201 2 W201 PPInsert filmment just cast the 528, then click (K* R*Load Filmment* S1		≥ G-Code Console		0.1 Y+0.1 > Y+1 >		Preheat Bec	
3 100/15220 4 200		E G-Code Files		0.1 Z+0.1 > Z+1 >		Preheat Bec	, PLA
5 (5 W 24 F 10 80 (0 H		Ø Macros				Miscellane	tous
7 22880 8 2009430		Filaments	A The following axes are not hom	ed: X, Y, Z		an 0 💉 🤷	
9 9000		© Settings		Extruder Control			
11 000 12			Feed amount in mm:		* Retract		
	X Cancel ✓ Save Changes		100 50 20 10 5 1	60 30 15 5 1	Extrude		
	Carlot Save Charges						

- If you are getting GCODE for the MACRO from another location (such as the SeeMeCNC Github), select the gcode you want to run when the macro is executed. Right click on the selected text, and click "Copy".
- Right click on the text area for the macro and click "Paste". Make sure all the text is correct, then click "Save Changes"
- The Macro is now available to run from the macro list, or from "Machine Control" tab under "User-Defined Macros"

Step 3 — Method 2: Uploading a Macro file

													s51			ament Load	×						Byers	0 - +	
Arternis51 x (× × = 10	C+ Disco		end G-Code	1 10			◆ Upload & Print Artemis51			1 🛕 🛛 Idle					
C+ Disconn		id G-Code		✓ ⊀ Send	🛧 Upload	& Print	Artemis5	51 🔺	Idle	_	ency STOP	≁ Tools	। अ Heater	rs / 🕂 Extr	a	≡ Contr		Temperature Ch			Machine Sta				
F Tools /	 Heaters 	/ + Extra	=	Control All -	Temperatu	re Chart		Machine Sta	us			Tool	Heater	Current	Activ	/e S	tandby	250			Head Position	x	Y	z	
Tool	Heater	Current	Active	Standby	250			Head Position	x	Y Z		Tool 0 -	Heater 1 active	25.3 °C	0 °C	• 0	•	200			Extruder Drives	n/a Drive 0	n/a Drive 1	n/a	
Tool 0 -	Heater 1	27.3 °C	0 •	0 -	200				n/a	n/a	n/a	Tool 1+	Heater 1 active Heater 0		0 •	• 0	•	150				n/a	0.0	0.0	
Tool 1 -	Heater 1	27.3 °C	0 -	0 -		Extruder Drives	Drive 0	Drive 1		Bed	0	•				50			Sensors	Vin		Z-Probe			
T1 active Bed Heater 0	22.1.10	23.1 °C 0 •						n/a Vin	0.0	0.0 Z-Probe		011				0 Auto Delta Calibration			00110010	13.0 V		0			
Beu	off	23.1 °C	0		0	0			130	V 0		A Machine Control		Head Movement					d Movement		User-Defi	efined Macros			
Machine	Control	🖀 Mar	cros Directory				📽 Go Up	♦ Upload	Macro File(s) + Ma	ake new +	🖨 Print S	Status		Home All		Home X	Home	Y	Home Z		Filam	ent Load		
Print Sta				-				<	X-10	« X-1	K X-0.1	X+0.1 >	X+1 > X+10 3			First Probe									
Fint Ste	1105		Filament Loa			Size		nodified				≥_ G-Coo	<	Y-10		< Y-0.1	Y+0.1 >	1 > Y+1 > Y+			Preheat Bed ABS				
G-Code	Console			10								G-Coo		Z-10	4 Z-1	≮ Z-0.1	Z+0.1 >	Z+1 >	Z+10 >		Preheat Bed PLA				
G-Code	Files		First Probe			247 B		2017, 2:48:09 F			-	& Macro	IS		2-10	• 2-1	\$ 2.0.1	240.1 #	271 7	2+10 /		Misce	ellaneous		
8 Macros			Preheat Bed			47 B		2017, 7:06:24 F				© Filame	ents	۸T	A The following axes are not homed: X, Y, Z								0%		
Filamen	ts		Preheat Bed PLA 45 B 12/28/2017, 7:06:24 PM						M			qs				Extr	xtruder Control				1	,			
															amount in	_									
Settings																_		Feedrate in mm/sec: ↑ Retract 60 30 15 5 1 ↓ Extrude							

- If you already have your macro saved to a file on your computer, you can upload it directly. (It must be a .gcode file)
- Click on the "Macros" tab on the left, then on "Upload Macro File(s)" on the right.
- Select your macro(s) for uploading.
- They will now be available in the macro list and under "User Defined Macros" on the Machine Control tab.